

Discovery Firmware Version 50P1 Release Notes

Tuesday, February 04, 2014

Diver's Release Notes

This section enumerates the changes from V50 to V50P1 that would be of interest to a diver of the rig.

1. Fixes a bug whereby in rare cases the solenoids can be triggered until the first validation.

Required Update actions

This section enumerates any changes that the diver must perform as a result of upgrading to V50P1.

1. Enclosed we have two firmware files
 - a. v50p01_all.enc is for the complete system.
 - b. v50p01_batt.enc is for battery only, in case you have multiple batteries.

Known Issues

This section describes known issues that a diver may experience.

1. None