



Technical bulletin 2011-10-1 – Poseidon Diving Systems AB

To whom it may concern.

Product: Poseidon MkVI Rebreather Electronics Module

Firmware version: <V46

Manufacturer: Poseidon Diving Systems AB

Manufactured between: 2009-01-01 – 2011-10-14

Number of incidents reported: 0

Number of reported injuries: 0

Summary

It has been found that Poseidon MkVI rarely but occurring fails pre dive test 38 without any evident hardware problems. Due to these circumstances a patched version of V46 is now released that solves this inconvenience. The firmware is named; V46 P1, please refer to image 1 below.

Recommendations

To update your Poseidon MkVi, do the following:

1. Download or update the latest version of the PC Config tool.
2. Connect you Poseidon MkVi to the PC through the IrDA link
3. Choose firmware v46P01.enc
4. Download the firmware into the Poseidon MkVI

Tools

Updated PC Config and computer with IR Dongle



Image 1

If you require assistance doing the above procedure, please contact the dive shop where you purchased your Discovery unit or the nearest Poseidon Discovery Service Center.

If you require additional assistance or have questions about this technical bulletin, please feel free to contact our support department at support@poseidon.com

Jörgen Nilsson

Quality Manager

Poseidon Diving Systems AB

P.O Box 8050

421 08 Västra Frölunda

Sweden

Jonas Brandt

CTO

Phone: +46 (0)31 734 2900

Fax: +46 (0)31 734 2901

E-mail: info@poseidon.com

Web : www.poseidon.com